

IZAR@CENTER 1.13b119 / MBus 1.41b60 / Device list 16.10.2012

New functions:

- additional Hungarian language
-

IZAR@CENTER 1.12b118 / MBus 1.41b60 / Device list 16.05.2012

New functions:

- Izar Receiver MBus support

Bug fixes:

- SPDE address interpretation
-

IZAR@CENTER 1.12b108 / MBus 1.39b45 / Device 15.11.2010

New functions:

- IZAR RRF 868/434 support
- DLL: SPDE address interpretation
-

Bug fixes:

- false Read out retries count when reading Hydro Center memory
- telegram interpretation bug fix

Notes

- SPDE address interpretation only work with IZAR CENTER not with old HYDRO CENTER.
- Exports of SPDE address to HydroNet don't work properly. Export not recommended, use IZAR@NET instead.

- SW also tested under Windows Vista as administrator and normal user
-

IZAR@CENTER 1.11b107 / MBus 1.39b45 / Device list 15.11.2010

Notes:

- New device list (see device list description file)
-

IZAR@CENTER 1.11b107 / MBus 1.39b45 / Device list 06.07.2010

New functions:

- Errors during import of device list are recognized and the user can decide to read the list again.
- New Russian text.
- DLL: Old alternative string VIF format
- DLL: Automatic mode for string VIF interpretation
- DLL: New medium according M-Bus norm.
- DLL: Corrected FD table according M-Bus norm.
- DLL: new string table handling.

Bug fixes:

- export to HydroNet (direct)
- export to HydroNet (file)

Notes:

- IZAR CENTER can't interpret correctly the alternative string VIF format. On meter with this format alarms are configurable but IZAR CENTER don't monitor this alarms right. (Like "elvaco" temperature sensors)